



Do not scale from this drawing. Any figure dimensions are to be taken from this drawing.
 The contractor shall verify all dimensions on site before commencing any work or any change.
 The contractor shall verify all dimensions on site before commencing any work or any change.
 The contractor shall verify all dimensions on site before commencing any work or any change.
 The contractor shall verify all dimensions on site before commencing any work or any change.
 The contractor shall verify all dimensions on site before commencing any work or any change.

Ordnance Survey Licence No. 100002962

DATE	05.02.21	PK	Revisions line added
BY	10/02/21	CE	Revised for approval
NO	001	PK	add/omit

bhd
 partnership
 Architecture • Engineering
 Arty Hill House, Wakefield Lane,
 Wakefield, Wetherby, WF8 7DB
 T: +44(0)1924 664971 F: +44(0)1924 660033
 E: general@bhdpartnership.com

DATE	Mr J & Mrs C Lawson		
NO	Deepdale Farm Keldholme York YO62 6NQ		
NO	Existing Block Plan		
NO	Preliminary		
NO	C Epton	DATE	09/09/20
NO	1:5000 A1	NO	D11881-02
NO	B		

Block Plan
 Scale 1:500

Ordnance Survey Licence No. 100002962